



**Available for Hyundai & Kia
NCF29AEM**



New software

NCF29AEM

Activation of the NCF29AEM software requires a payment of \$250 USD. Once payment is made, the serial number must be sent to the authorized distributor. The payment includes access to NCF29AEM updates; current updates will be added monthly.



95440-N9500
Hyundai Tucson
5B.



95440-N9550
Hyundai Tucson
4B.



95440-N9520
Hyundai Tucson
3B.



95440-N9570
Hyundai Tucson
5B.



95440-L1510
Hyundai Sonata
5B.



95440-L5700
Hyundai Sonata
4B.



95440-L1710
Hyundai Sonata
5B.



95440-L1760
Hyundai Sonata
5B.



95440-L5750
Hyundai Sonata
4B.



95440-L1810
Hyundai Sonata
4B.



95440-P6010
Hyundai Santa Fe
4B.



95440-P6040
Hyundai Santa Fe
5B.



95440-P6050
Hyundai Santa Fe
5B.



95440-P9050
Hyundai Palaside
5B.



95440-P9070
Hyundai Palaside
5B.



HYUNDAI



95440-R0910
Kia Carnival
6B.



95440-R0800
Kia Carnival
5B.



95440-R0900
Kia Carnival
4B.



95440-R0810
Kia Carnival
7B.



95440-R0840
Kia Carnival
7B.



About the NCF29AEM Software:

Activation of the NCF29AEM software requires a payment of \$250 USD. Once payment is made, the serial number must be sent to the authorized distributor. The payment includes access to NCF29AEM updates; current updates will be added monthly.